


1		2		3		4		5		6		7		8	
TRANCEMISSION TYPE		GRADE		Part No.		PRODUCT NAME									
SINGLE-MODE		Super Low Loss		90A11619		16MT-PA-SLS(NB)-SI									
				90A11613		16MT-PA-SLS(NB)-SI-WOB									
		Standard Loss		90A11622		16MT-PA-S(NB)									
				90A11624		16MT-PA-S(NB)-WOB									
MULTIMODE		Super Low Loss		90A11585		16MT-PA-SLM(NB)									
				90A11625		16MT-PF-SLM(NB)									
		Standard Loss		90A11499		16MT-PF-M(NB)									
				90A11500		16MT-PF-M(NB)-WOB									
16MT - P A - SLS (NB) - SI - WOB ① ② ③ ④ ⑤ ⑥ ① : Connector fiber count - 16MT : 16 fiber counts MT ferrule ② : MT Material - P : PPS ③ : Polishing - A : For Angle polishing F : For Flat Polishing ④ : Grade - SLS : Super Low Loss Single-mode S : Standard Loss Single-mode SLM : Super Low Loss Multimode M : Standard Loss Multimode ⑤ : Condition 1 - SI : Sampling Inspection ⑥ : Condition 2 - WOB : Without Boot															
NOTES; 1. This document shows the outline of our MT ferrule and boot with the Parts Number table. Please contact us for customers' drawing to show specific dimensions if necessary.															
1 2025.07.24 Create a new. H.Ohta REV DATE REVISION RECORD BY APPROVED BY T.Saitoh SECTION HEAD H.Ohta CHIEFING CHECKED BY DESIGNED BY H.Ohta COPIED BY HAKUSAN UNIT m m SCALE 5 / 1 TRIANGLE PROJECTION DATE 24, Jul. 2025 NAME 16MT Connector series Lineup DRAWING No. 90A11656															
1		2		3		4		5		6		7		8	



1	2	3	4	5	6	7	8
TRANCEMISSION TYPE		GRADE	Part No.	PRODUCT NAME			
MULTIMODE	Super Low Loss	90A11648	32MT-PA-SLM(NB)				
		90A11647	32MT-PF-SLM(NB)				
	Standard Loss	90A11503	32MT-PF-M(NB)				
		90A11504	32MT-PF-M(NB)-WOB				
32MT - P F - M (NB) - WOB ① ② ③ ④ ⑤ ① : Connector fiber count - 32MT : 32 fiber counts MT ferrule ② : MT Material - P : PPS ③ : Polishing - A : For Angle polishing F : For Flat Polishing ④ : Grade - SLM : Super Low Loss Multimode M : Standard Loss Multimode ⑤ : Condition - WOB : Without Boot					【MT Ferrule】		

32MT	-	P	F	-	M	(NB)	-	WOB
①		②	③		④			⑤

- ① : Connector fiber count

- 32MT : 32 fiber counts MT ferrule
- ② : MT Material

- P : PPS
- ③ : Polishing

- A : For Angle polishing

- F : For Flat Polishing
- ④ : Grade

- SLM : Super Low Loss Multimode

- M : Standard Loss Multimode
- ⑤ : Condition

- WOB : Without Boot

NOTES;

1. This document shows the outline of our MT ferrule and boot with the Parts Number table.

Please contact us for customers' drawing to show specific dimensions if necessary.

1	2025.07.24	Create a new.	H.Ohta
REV	DATE	REVISION RECORD	BY

APPROVED BY	T.Saitoh	UNIT	m m	DATE	24, Jul. 2025
SECTION HEAD	H.Ohta			NAME	32MT Connector series Lineup
CHIEFING					
CHECKED BY					
DESIGNED BY	H.Ohta	TRIANGLE PROJECTION	DRAWING No.	90A11658	
COPIED BY					
 HAKUSAN					